

# NATF Redacted Operating Experience Report

Safety - Caisson Drop Accident

### About NATF Redacted Operating Experience (OE) Reports

North American Transmission Forum (NATF) operating experience reports highlight positive or negative transmission (reliability or resiliency) experiences worth sharing for learning opportunities or potential trending. The overall goal is to help each other learn without experiencing the same issues first-hand. This sharing originates confidentially within the NATF membership.

Redacted operating experience reports are posted on the NATF public website to allow the NATF and its members to more broadly share information, especially safety-related alerts and learnings, with contractors and other utilities to benefit the industry at large.

The NATF member company that submitted the initial restricted distribution OE report for this topic/event has approved the NATF to issue this redacted OE report.

### **Open Distribution**

Copyright © 2018 North American Transmission Forum. Not for sale or commercial use. All rights reserved.

### Disclaimer

This document was created by the North American Transmission Forum (NATF) to facilitate industry work to improve reliability and resiliency. The NATF reserves the right to make changes to the information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. "North American Transmission Forum" and its associated logo are trademarks of NATF. Other product and brand names may be trademarks of their respective owners. This legend should not be removed from the document.



# **Topic**

Caisson Drop Accident

# Description

An employee jumped from an off-road 150-ton crane onto a matting below causing a significant injury. The employee jumped because a 35,000 lb. caisson fell from a rigging and landed on the crane, which caused an extensive amount of damage to the crane.

### Lessons Learned

- 1. Crews failed to follow the approved work plan for caisson installation, which was due to a lack of communication between contract groups and a lack of oversight by both parties.
- 2. Material ordered for the job did not meet our company specifications.
- 3. A lack of communication and observation to ensure compliance contributed to event.

### **Actions Taken**

- Shut job down for three weeks while the investigation took place and a return-to-work plan was submitted and vetted.
- Ensured that crews had a detailed plan on how to comply with maintaining positive control at all times for all subsequent caissons lifted.
- Sub-contractor changed out previous crew and had management on-site for remainder of work.
- Additional oversight was required at all times by prime contractor and our project management.

### Extent of Condition

Our safety and operations leadership developed a safety alert and best practices presentation and distributed throughout all affected workgroups. Our safety department also developed a caisson installation field guide to help crews ensure that all steps are taken to complete this task safely.

### Additional Information

### Redacted Safety Presentation and Installation Field Guide

Please see subsequent pages of this report for a summarized presentation and a caisson installation field guide.



# Transmission Caisson Drop

# What was the Safety Event?

- Extensive damage to crane from 35,000 lb. caisson falling off of rigging and impacting crane.
- Significant injury caused by employee jumping from offroad 150 ton crane onto matting below.

# Damage to crane.





# Crane and spot that employee fell onto.



# How did the Safety Event Occur?

- Deviation from pre-approved execution plan of the job.
- Lack of communication between prime contractor to subcontractor of expected execution plan.
- Improper job setup.
- · Oversight did not catch issues prior to event.



# How did the Safety Event Occur?

- Deviation from plan allowed crew to use machinery in a way manufacture did not intend and warned against.
- Driving ears on the caisson came improperly coated with galvanizing from the manufacture. This caused the teeth of the vibratory hammer to get fouled by galvanizing.

# Galvanizing on caisson ears.





# **Key Learnings**

- Crews failed to follow approved work plan for caisson installation this was due to a lack of communication between contract groups and a lack of oversight by both parties.
- · Material ordered for job did not meet our specifications.
- Lack of communication and observation to ensure compliance contributed to event.



# Caisson Installation Field Guide

## **Key Things to Remember:**

Know the crane's failure zone

2 Know the grapple's failure zone

3

Know the vibratory hammer's failure zone

Apart from operators in equipment cabs, keep all personnel out of failure zones.

STAY OUT OF THE LINE OF FIRE.

# **HAZARDS**

What could go wrong?

### **Equipment failure**

- · Develop a Lift Plan.
- · Ensure equipment and rigging have adequate capacity.
- · Verify ground stability checks are completed.
- Use only certified crane operators.

# Applies to Conses, Derricks, and Power-Operated egapinment that can be used to hold, Inwer and/or hostoantally move a superated food (includes accuration, feelbly, flowph Terrain epigement, holds, etc., when used with ripping). Operator Equipment Makin/Model Crane Certification Date Facility/Newa Job Description List items being illhed and associated weights Crame's max rated Max radius to be used Tomme's max rated Max radius to be used Boom length Rated capacity from load So of capacity Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 131/14, Ning operations to present ming. Estimated wind speed 141/14, Norther Stated capacity Norther Stated capacity 141/14, Norther Stated ca

# CONTROL MEASURES

What can I do?



# Material falls during lift

- Set up the worksite to ensure positive controls are maintained such as grapple crane or crane with rigging at all times.
- Inspect slings and rigging prior to use.
- . Do not use quick connect rigging, until the caisson is set.
- . Do not use the hammer without the grapple.
- · Pick up caisson from side opposite other operations.
- · Use tag line or push sticks to control load.



Barricade failure zone, load travel path, and landing area.
Maintain safe distance (greater than caisson length) during lift.
Do not stand beneath boom or hammer.
Use trained signallers.



# HAZARDS What could go wrong?

# **CONTROL MEASURES**

What can I do?

