

NATF Redacted Operating Experience Report

Vehicle Fire Caused by Propane Torch

About NATF Redacted Operating Experience (OE) Reports

North American Transmission Forum (NATF) operating experience reports highlight positive or negative transmission (reliability or resiliency) experiences worth sharing for learning opportunities or potential trending. The overall goal is to help each other learn without experiencing the same issues first-hand. This sharing originates confidentially within the NATF membership.

Redacted operating experience reports are posted on the NATF public website to allow the NATF and its members to more broadly share information, especially safety-related alerts and learnings, with contractors and other utilities to benefit the industry at large.

The NATF member company that submitted the initial restricted distribution OE report for this topic/event has approved the NATF to issue this redacted OE report.

Open Distribution

Copyright © 2020 North American Transmission Forum. Not for sale or commercial use. All rights reserved.

Disclaime

This document was created by the North American Transmission Forum (NATF) to facilitate industry work to improve reliability and resiliency. The NATF reserves the right to make changes to the information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an "as is" basis. "North American Transmission Forum" and its associated logo are trademarks of NATF. Other product and brand names may be trademarks of their respective owners. This legend should not be removed from the document.



Topic

Vehicle Fire Caused by Propane Torch

Description

A disposable propane torch was being used to thaw an air line on a breaker within a substation yard. The torch stopped working because of the cold ambient temperature (estimated to be -11°F), which condensed the propane. The torch (bottle and nozzle) was turned off and placed on the dash of the truck with the heater on, for the purpose of thawing and expanding the frozen propane gas. A small fire resulted, which was immediately extinguished with snow. A fire extinguisher was available but was not required. No injuries or impact to customers occurred.



View of the burned area of the truck dashboard. Snow was used to extinguish the fire.

Reference: NATF-OER-569



Lessons Learned

- 1. Propane torches should not be placed on the dashboards of vehicles.
- 2. Thawing propane cylinders on dashboard heating vents is not a good practice and should not be used in the future.
- 3. Housekeeping of vehicle dashboards/interiors was considered a contributing factor.
- 4. Propane torch tips need to cool completely before being left unattended and must be kept far away from combustibles.
- 5. Training and protocols regarding the proper storage and use of propane bottles are critical for all employees using these tools.

Actions Taken

- 1. Crew extinguished the fire and removed the propane tank from the truck cab to establish a safe environment.
- 2. Initiated a work stand-down removed the vehicle from service for repair.
- 3. Performed a "learning opportunity" review with a field-staff team; also reviewed and shared the NATF redacted OER-366 "Disposable Portable Propane Tank Storage" report.
- 4. Implemented corrective actions including (a) training for personnel and (b) brass caps with O-rings were acquired for use during storage.
- 5. Communicated all results with other personnel.
- 6. Considering alternative methods, such as heat guns, to thaw/heat frozen devices.
- 7. Brass caps with O-rings were issued to be used when the tank is in storage.
- 8. Propane storage and usage will be included in new training programs.

Extent of Condition

A full inventory of portable propane tanks was performed.

Reference: NATF-OER-569